Capture Ant EQITO a QC

Inspection Note of Er.Arun Pathania, Superintending Engineer, National

Mighway Circle, HPPWD., Shahpur for the month of August, 2020.

During the visit of the N.H Division, HP.PWD., Hamirpur on 09-08-2020, following roads were ingrested:

following roads were inspected:-

. Periodical Renewal work from km.90/0 to 100/00 of NH-70 (New NH-03)in the state of H.P under Annual Renewal Program (ARP)for the year 2019-20

318/20

The work was awarded to Sh.Deepak Joshi, Govt. Contractor vide Executive Engineer, N.H. Hamirpur Division letter No.8405-16, dated 15-10-2019. The tarring work has been completed by the Contractor December, 2019. During the inspection it was observed that black top surface has been damaged badly in many reaches which seems to be due to poor work manship and tack_coat. It also seems that quality of bitumen may also be not good. The Executive Engineer has been advised to notify that exact quantum of damaged potion in writing to the Contractor and ask him to repair it in the month of September, 2020 and compliance report be submitted to this office. In the meanwhile copies of tests conducted during construction on the work relating to BC and bitumen be supplied to this office. The Quantity of bitumen purchased by the Contractor & consumed on the work may also be verified.

2. <u>Periodical Renewal work from 80/0 to 90/0 of NH-70(New-03)in the State of HP under Annuqal Renewal Program(ARP)for the year 20129-20</u>

This work has been awarded to M/S S.S. Chouhan Construction Pvt Ltd., Vide Executive Engineer, National Highway Division, HP.PWD., Hamirpur letter No.5973-80, dated 04-09-2019. The work has been partially completed by the Contractor but it has been seen that the work is of poor quality and at many places tarred surface has caused slippage

and so many pot holes have developed. The Executive Engineer, N.H. Hamirpur has been asked to notify the

exact quantum of damaged portion in writing to the Contractor and ask him to repair it in the month of September, 2020 and compliance report be submitted to this office. In the meanwhile copiers of tests conducted during construction on the work relating to BC and bitumen be supplied to this office. The quantity of bitumen purchased by the Contractor & consumed on the work may also be verified.

3. Improvement of Black Spot:

12 Nos black spot as per list of Ministry are being improved in Hamirpur Division TBM in all the black spots have been laid and work of installing warning signs and solar blinkers was going on. The Assistant Engineer, N.H. Dehra, Amb and Una Sub Divisions were instructed to complete the works of improvement of black spots at the earliest and upload their status on the Website. & compliance be reported to this office.

Superintending Engineer, N.H. Circle, HP.PWD., Shahpur.

No.PW-SENH/Inspection Note/2019-20-762-66 Dated: 29/5/20

1. Copy to the Engineer-in-Chief (Project), HP.PWD., Shimla for information please.

2. Copy to th Chief Engineer, N.H. HPWD., Shimla for information.

3. Copy to the Executive Engineer, Hamirpur Division, HP.PWD., Hamirpur for information and necessary action. He is requested to look into the matter personally and report thereof be sent to this office immediately.

4. Copy to Drawing Branch/Work Section of this office.

Superintending Engineer, N.H. Circle, HP PWD.,

Shahpur