INSPECTION NOTE RECORDED BY EAS.K.SH CHIEF ENGINEER (KZ), HP. EWD. DHARAMSHAI

Name of work:-

C/O 30.00 Mtrs. Span double lane bridge over Salandri Nallah on Bathri

Sundle Langera J & K boundary road at RD.22/270.

Date of Inspection:

30.072020 Name of Inspection Officer: -

Designation: -

Er.S.K.Sharma

Rs.313.39 lacs

Chief Engineer (KZ)

A/A & E/S:-

Accorded vide letter No.RW/NH-12037/164/2002/HP/NH-1(Vol-

(IV) dated 23.05.2017.

Awarded amount:-Date of Award :-

Date of start:-Date of completion: -

06.03.2018 05.03.2020

20.02.2018

Expenditure upto date Accompanying officers: -

Rs.308.84 lacs

1.Er.D.S.Pathania, S.E.7th Circle, HPPWD. Dalhousie. 2.Er Suresh Chandel, EE, HPPWD.Salooni Division. 3.Er.Buphinder Singh, A.E.HPPWD. Sub D.vn. Bhali 4. Er Sandeep Kumar, JE, HPPWD. Sub Diva. Bhali

Representative: M/S National Construction Co.(India),128 Sector-

25, Panchkula, Hariyana.

The said work was inspected by the undersigned alongwith all the above named Officers/officials. At the time of inspection, sub-structure & super structure work completed and work of approach slab was in progress. During the course of the inspection following observations/short comings were noticed.

- The work is in advance stage of completion. The contractor has assured to complete the work before 30th September, 2020. The Executive Engineer is directed to ensure the completion of this work by the said date. He is further advised to obtain the revised working programme from the contractor or else take the action as per various clauses of the agreement, if the reasons given by the contractor are not tenable.
- The exact location of the C.C.cube samples tested have not been mentioned in the quality control register. It should be ensured in future that such mistakes are not repeated.
- The calibration certificate of the C.T.M machine was not shown to the undersigned during my visit, 3 though the Engineer of the contractor stated that the same is available with him. He is directed to show it to the Superintending Engineer, HPPWD.7th Circle Dalhousie within seven days for scrutiny/checking. It is also noticed that hooks of the links/stirrup in dirt wall have not been bent to 360 degree, this rectification should be done immediately.

(S.K.Sharma) Chief Engineer (KZ), HP.PV/D.Dharamshala.

Endst.PW/CE(KZ)/Insp.Note/2020- /5-39-43 Dated: 5/Copy to The Principal Secretary (PW) to Govt. of H.P.Shimla for information. Dated: 5/8/20

Copy to the Engineer-in-Chief, HP.PWD.Nirman Bhawan, and Nigam Vihar Shimla for information please.

Copy to the Engineer-in-Chief (Project), HPPWD.Nigam Vihar Shimla-171002 for information please. Copy to the Superintending Engineer, 7th Circle HP.PWD.Dalhousie for information and necessary action. Copy to the Executive Engineer, HPPWD. Division Salooni for information and accessary action.

> (S.K.Sharma) Chief Engineer (KZ), HP.PWD.Dharamshala.

CHIEF ENGINEER (KZ), HP. PWD. DHARAMSHA

Name of work:-

C/O 40.00 mtrs. Span double lane bridge over Rollah nallah on Bathri

Sundla Langera J&K boundary road at RD.22/970.(MDR-35) Under CRF.

Date of Inspection:

Name of Inspection Officer: -

Designation: -

Er.S.K.Sharma

30.072020

Chief Engineer (KZ)

Accorded vide letter No.RW/NH-12037/164/2002/HP/NH-1(Vol-A/A & E/S:-

IV) dated 23.05.2017.

Awarded amount:-

Date of Award :-Date of start:-

Date of completion: -Expenditure upto date

Accompanying officers: -

Rs.406.52 lacs

20.04.2018 04.05.2018 03.05.2020

Rs.287.20 lacs

1.Er.D.S.Pathania, S.E.7th Circle, HPPWD. Dalhousie. 2.Er.Suresh Chandel, EE, HPPWD.Salooni Division. 3.Er. Buphinder Singh, A.E. HPPWD. Sub Divin Bhali

4.Er. Sandeep Kumar, JE, HPPWD. Sub Divi: Bhali

Representative: M/S National India Construction Co.Jalandhar Byepass

road Simble Chowk, Pathankot-145001.

The said work was inspected by the undersigned alongwith all the above named Officers/officials. At the time of inspection, during the course of the inspection following observations/short comings were noticed. Both sides abutments completed & bed block casted & work of super structure stands completed, the work of approaches & railing is in progress.

This work is in advance stage of completion. The contractor has assured to complete the work before 30th September, 2020. The Executive Engineer is directed to ensure the completion of this work by the said date. He is further advised to obtain the revised working programme from the contractor or else take the action as per the various clauses of the agreement, if the reasons given by the contractor are not tenable.

The exact location of the C.C.cube samples tested have not been mentioned in the quality control

register. It should be ensured in future that such mistakes are not repeated.

The calibration certificate of the C.T.M machine was not shown to the undersigned during my visit, though the Engineer of the contractor stated that the same is available with him. He is directed to show it to the Superintending Engineer, HPPWD.7th Circle Dalhousie within seven days for scrutiny/checking. It is also noticed that hooks of the links/stirrup dirt wall have not been bent to 360 degree, this rectification should be done immediately.

The shelf life of the plasticizer being used should be ensured before the same is used in the

concrete work.

(S.K.Sharma) Chief Engineer (KZ), HP.PWD.Dharamshala.

Endst.PW/CE(KZ)/Insp.Note/2020-

Dated: 5/8/20

Copy to The Principal Secretary (PW) to Govt. of H.P.Shimla for information.

Copy to the Engineer-in-Chief, HP.PWD.Nirman Bhawan, and Nigam Vihar Shimla for information

Copy to the Engineer-in-Chief (Project), HPPWD.Nigam Vihar Shimla-171002 for information please. Copy to the Superintending Engineer, 7th Circle HP.PWD.Dalhousie for information and necessary action.

Copy to the Executive Engineer, HPPWD.Division Salooni for information and necessary action.

Chief Engineer (KZ), HP.PWD.Dharamshala.